Jefferson Lab
Thomas Jefferson National Accelerator Facility
Exploring the Nature of Matter

ESH&Q Manual

3210-T3 Task Hazard Analysis Worksheet

Task Title:_remove sane prototype from room 126
Task #:C-08-019-T
Page 1 of 1
Date 4-09-08

Complete all information. Use as many sheets as necessary.	
Task location:	Prepared by: J Nines
Division: PHY	Reviewed by(worker): Larry Gaveney
Department: Hall C	Reviewed by (worker):
Supervisor: W. Kellner	Approved by:
Standard Requirements: Safety Shoes, Forklift	

Sequence of Job Steps	Potential Hazards	Risk Code before mitigation	Safety Procedures/Practices/ Controls	Risk Code after mitigation
Moove Cabinets	Tip over	1	Use Two People Be careful	0
Drive Forklift in	Smash Cabinet	1	Have a Spotter Drive Slow	0
Lift sane Prototype	Drop	2	Make Shure Load is Secure.	0
Lower Prototype To Floor	Drop	2	see Above Line	0
Roll Prototype out	Crash into Cabinet	1	go Slow Be careful	0
Transport To Test Lab	Drop	2	Secure load To Lift go Slow	0