Task: Crane HES Dipole Sections
Task #: C-08-025-T
Date: 6-17-08

Complete all information. Use as many sheets as necessary.	
Task location: Hall C	Frequency of use:
Division: PHY	Prepared by: J Carucci
Department: Hall C	Reviewed by (employee): C Lassiter
Supervisor: W. Kellner	Approved by:
Standard Requirements: (PPE, TOSPs, SOPs, etc.)Hardhats, safety shoes, gloves. Journeyman rigger and crane operator. Follow standard rigging procedures and EH&S 6140 Crane & Hoist.	

Sequence of Job Steps	Potential Hazards	Risk Code before mitigation	Safety Procedures/Practices/ Controls	Risk Code after mitigation
Rig for 36000 pds.	Pinch	2	Riggers should be careful & wear gloves	0
Lift load & crane over HMS	Load may drop/tip etc.	2	Use certified crane operator, check all rigging, use spotters	0
Set load on floor	Pinch/ crush	2	Move slowly make sure all is clear	0
	Damage pole faces	2	Use clean rubber pads (at least 3/8" thick) between pole face and cribbing.	0

When a completed analysis indicates that the estimated risk code for any of the steps of this task is "medium" or higher (RC≥3), then develop a formal written procedure for the task and have it reviewed and approved prior to beginning the work.