

Task Title: Move Target Tripod

Task #: C-08-016-T

Date: 03/06/08

Complete all information. Use as many sheets as necessary.	
Task location: Hall C/EEL/Test Lab	Prepared by: A. Kenyon
Division: PHY	Reviewed by (worker): <i>[Signature]</i>
Department: Hall C	Reviewed by (worker): <i>Charles Lassiter</i>
Supervisor: W. Kellner	Approved by: <i>[Signature]</i>
Standard Requirements: Hardhats, safety shoes, gloves. Journeyman rigger and crane operator. Follow standard rigging procedures and EH&S 6140 Crane & Hoist, 6147 Aerial Work Platforms, 6132 Ladders and Scaffolds, 6145 Fork Lift, and 6131 Trip and Fall Protection	

Sequence of Job Steps	Potential Hazards	Risk Code before mitigation	Safety Procedures/Practices/Controls	Risk Code after mitigation
Rig	Drop (est 2000 lbs)	3	Inspect all rigging prior to use. Use appropriate rigging	1
Lift	Overhead	3	Use spotters to ensure no one goes under the load.	1
	Bump	1	Center hook on load prior to lifting	0
Invert (if needed)	Slip	2	Double wrap chocker to prevent slippage	0
	Sudden swing	2	Lift as close to center of gravity as possible.	0
Collapse legs (if needed)	Pinch	1	Watch your fingers	0
Forklift from top	Obstructed view	2	Drive backwards	0
	Sliding	1	Tilt the load only as much as needed	0