

Hall C

Aerial Platform Inspection

Aerial Platform: <u>Grove</u> Shift: <u>15T</u>

Date: 4/-1-08

BEDALL

OFO 401 brove Inspection		
Complete all information. Add sheets if necessary. Use NA if not applicable.		
Aerial Platform Location:	Department: Hall C	
Division: PHY	Inspected by (print): Vines	
Supervisor: W. Kellner	Inspected by (sign): Mine	
Refer to EH&S 6147 T1 and operator's manual for procedure. Perform inspection prior to initial use		
for a given shift. If aerial platform any aspect immediately report to supervisor.		

V	Description	Comments
V	Visually inspect tires.	
V	Visually inspect pumps, hoses, and cylinders.	
V	Visually inspect batteries and electricals.	
V	Visually inspect all joints.	
V	Visually inspect ground controls.	
V	Confirm all ground controls work.	14° /
V	Visually inspect platform controls.	
	Confirm horn works.	*
	Confirm all articulations work.	
1	Confirm speed control works.	
/	Confirm driving and steering work.	
V	Confirm warning beacon works.	
V	Confirm warning sound works.	