

Hall C

Crane/Hoist Inspection

Crane/Hoist: 5 HOP
Shift: PAT

Date: 5/21/08

Complete all information. Add sheets if necessary. Use NA if not applicable.		
Crane/Hoist Location: A PARICE 5 40P	oist Location: A PARICE 5 40? Department: Hall C	
Division: PHY	Inspected by (print): LARRY CARRAWAY	
Supervisor: W. Kellner	Inspected by (sign): Tany (foliamay	
Refer to EH&S 6140 T1 for procedure. Perform inspection at the beginning of each shift that the		
crane/hoist will be used. If crane/hoist fails any aspect immediately report to supervisor.		

V	Description	Comments
/	Confirm disconnect de-energizes crane.	
NA	Confirm horn.	
/	Confirm hook speeds up/down.	
~/A	Confirm trolley speeds in/out.	
MA	Confirm bridge speeds cw/ccw.	
NA	Check lower hook limit.	
_	Visually inspect hook and snap.	
/	Visually inspect cable/chain.	
/	Visually inspect cable drum.	
/	Visually inspect trolley.	
/	Visually inspect bridge.	
/	Check crane upper limit.	
/	Check full range of trolley operation.	
/	Check full range of bridge operation.	

rev: March 19, 2008a