

Hall C

Crane/Hoist Inspection

Crane/Hoist:

Shift: PA Date: (2/4/0)

Complete all information. Add sheets if necessary. Use NA if not applicable.			
Crane/Hoist Location: Department: Hall C			
Division: PHY	Inspected by (print): Heryon		
Supervisor: W. Kellner	Inspected by (sign):		
Refer to EH&S 6140 T1 for procedure. Perform inspection at the beginning of each shift that the			
crane/hoist will be used. If crane/hoist fails any aspect immediately report to supervisor.			

1	Description	Comments
V	Confirm disconnect de-energizes crane.	
	Confirm horn.	
0	Confirm hook speeds up/down.	
V	Confirm trolley speeds in/out.	
0	Confirm bridge speeds cw/ccw.	
0	Check lower hook limit.	
/	Visually inspect hook and snap.	
V	Visually inspect cable/chain.	
/	Visually inspect cable drum.	
/	Visually inspect trolley.	
V	Visually inspect bridge.	
V	Check crane upper limit.	
1	Check full range of trolley operation.	
/	Check full range of bridge operation.	

rev: March 19, 2008a