

Hall C

## **Crane/Hoist Inspection**

Crane/Hoist: 201

Shift: DAY
Date: 4/1/09

Complete all information. Add sheets if necessary. Use NA if not applicable.		
Crane/Hoist Location:	Department: Hall C	
Division: PHY	Inspected by (print): LARRY CARRAWAY	
Supervisor: W. Kellner	Inspected by (sign): Luny anaway	
Refer to EH&S 6140 T1 for procedure. Perform inspection at the beginning of each shift that the		
crane/hoist will be used. If crane/hoist fails any aspect immediately report to supervisor.		

1	Description	Comments
	Confirm disconnect de-energizes crane.	
	Confirm horn.	
	Confirm hook speeds up/down.	
	Confirm trolley speeds in/out.	
	Confirm bridge speeds cw/ccw.	
	Check lower hook limit.	
	Visually inspect hook and snap.	
	Visually inspect cable/chain.	
/	Visually inspect cable drum.	
	Visually inspect trolley.	
	Visually inspect bridge.	
/	Check crane upper limit.	
	Check full range of trolley operation.	
/	Check full range of bridge operation.	