

only 200A above

start 11:46 - 5.5 GeV/c

start 12:02 - 4 GeV/c

start 12:20 - 2.5 GeV/c

start 12:34 - 1 GeV/c

start 12:48 -  $\phi$  S

start 13:00 -  $\phi$ .25

start 13:12 -  $\phi$ .125

13:20  $\phi$  PS on

13:35(?)  $\phi$  PS off

13:45 change to + polarity

13:46 ~~change~~ turn ~~on~~ on supply

13:01 start going to 1505 MBL

14:21 AT +5,5 with dipole

14:44 AT +4,0 with dipole

15:03 change to +2,5

15:20 change to +1,0

15:35 change to +0,5

15:54 change to +0,25