


A



Fit
coefficients

theta_s = 40

a0	49.06	T-cm
a1	-0.00925	
a2	0.01468	

0.3*a0 1.47E-001 T-m
0.3*a1 -2.78E-005
0.3*a2 4.40E-005

theta_s = 30

a0	62.85
a1	-0.0583
a2	0.0278

theta_s = 50

a0	36.27
a1	-0.0224
a2	0.0108